



SQAR's by Commodity Matrix

COMMODITY	SQAR's	Quality System Requirements		Quality Program Requirements			Control Of I, M & T Equipment			Right Of Access	Source Inspection	Gov't Source Inspection	Use Of Approved Source	Nonconforming Material	Require 100 % Inspection	Process Control Plan	Material Test Report	Certification Of Compliance	Certification Of Calibration	Cert Of Nondestructive Testing	First Article Inspection	Traceability	Shelf-Life Identification	Acceptance Data Package					Quality Records	Handling And Delivery	No Changes Allowed w/o Approval	Quality Flow Down to Sub-Tiers	FOD	ROHS	ITAR	Corrective Action Response		
		1 A	1 B	2 A	2 B	2 C	3 A	3 B	3 C	4	5	6	7	8	9	10	11 A	11 B	12	13	14	15	16	17	18 A	18 B	18 C	18 D	18 E	19	20	21	22	23	24	25	26	
Limited Life Items: chemicals, adhesives, o-rings	4, 12, 16, 17, 19, 20, 21, 22, 25, 26								X								X				X	X							X	X	X	X				X	X	
Machining, Stamping, Molding	1A, 3, 4, 8, 12, 15, 19, 20, 21, 22, 23, 25, 26	X						X	X				X					X			X									X	X	X	X	X			X	X
Connectors / Cable Assemblies	2A, 4, 8, 12, 16, 19, 20, 21, 22, 23, 25, 26			X					X				X					X				X								X	X	X	X	X			X	X
Diodes / PCB's	1A, 4, 8, 12, 16, 19, 20, 21, 22, 23, 25, 26	X							X				X					X				X								X	X	X	X	X			X	X
Standard Hardware	4, 8, 12, 19, 20, 21, 22, 26								X				X					X												X	X	X	X					X
Outside processing (Special processes)	1A, 4, 12, 19, 20, 21, 22, 25, 26	X							X									X												X	X	X	X				X	X
Raw Material	4, 11, 12, 19, 20, 21, 22, 26								X							X	X	X												X	X	X	X					X
Ceramic Capacitors	1A, 4, 8, 12, 16, 18A, 18C, 19, 20, 21, 22, 23, 25, 26	X							X				X					X				X		X		X			X	X	X	X	X			X	X	
Calibration	3, 4, 13, 19, 20, 21, 22, 26							X	X											X										X	X	X	X					X